

CERTIFICATE OF COMPLIANCE

Certificate Number 20161027- EX454
Report Reference EX454-19890616
Issue Date 2017-OCTOBER-23

Issued to: RELIABLE AUTOMATIC SPRINKLER CO INC
1470 SMITH GROVE RD
LIBERTY SC 29657

This is to certify that representative samples of SPRINKLERS, AUTOMATIC AND OPEN
See addendum page


Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 199, Automatic Sprinklers for Fire-Protection Service
ULC/ORD-C199-03, Automatic Sprinklers For Fire-Protection Service

Additional Information: See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutu/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20161027- EX454
Report Reference EX454-19890616
Issue Date 2017-OCTOBER-23

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Models:

Automatic sprinklers incorporating 3.0 mm frangible glass bulbs or Mini Links of the following models, types and temperature ratings; available with decorative zinc plated, black painted and bright brass with lacquer enamel, teflon, polyester coatings and stainless steel
SIN

R3611, R3613, R3615, R3621, R3623, R3625, , R5525, R3611,,R3613, R5615, R3685, R3635, R3615, R3615, R3625, R3635, R3615, R3625, R3635, R6834, R3615, R3625, R3635, R4845, R4865, R4862, R4842, R5942, R3612, R3622, R5612, R5622, R3615,R7095, R3612, R3611, R3613, R3615, R3635, R3615 , R4842, R5945, R4862, R5962, R5945, R5942, RA0362, RA1414, RA3614, RA1414, RA1425, RA3624, RA3634, , RA1435, RA1485, RA2614, RA3914, , RA3934 , , RA2625, RA3924, RA2845, RA2845, RA3045, RA3045, RA3195, RA1564, RA1564, RA1411, RA1421, RA1413, RA1423, RA5412, RA5422, RA6312, RA6322, RA6212, RA6222 RA5814, RA5914, R5814, R5914, RA6514,RA6524.RA6512,RA6522



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/about/locations/>

